Annexure D

BUILDING SAFETY CERTIFICATE

NO. JAVAK NO. / DM SECTION 3126

Dated: 10 06 12024

It is certified that the existing building .Anjand ... School ... I xellence ... (name of the building or premises) at .. G.u.L. No. 6. , Talesamon, Faliyohad. Asegaan Road, Asegan Chh: Sambha; كام المرادة (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1) 🗸	(2) 🗸	(3) V	(4) ~	(5)	(6)
No. of Floor(s) in the	_	_				
Block	4+2	at2	at2	4+2		

The building is owned/occupied by Smila Shankaz Palhal (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Sub. Division J. Enginees (Name of Govt.) on...05./.10./.20.3... (date of inspection) in ME Swazniet shankaz Palhal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from. 19.16.12.0.2.4... for a period of1...y.ea z..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Reference of Sub Divisional Engineer P. W. Sub Division (angoput) [7] ** Private 110/23]
2. After 1 year zevisit from government authority is required.
3. Ti-e. Echovation of this certificate is required.
4. Regular Maintenance of building is required.

Issued on .10/06/2024 at P.W. (West) D. by Chh. Sambhaji Naga E

* Strike out whichever is not applicable. In case of block is more than six use peparate sheet for detail.

Signature with Selly. (West) Division. Name at man sambh dhadar

Designation: Freative Engineer

Name & Address of Department/ Office: Ph. (Hest) Division, Chhateapali Sambhaji Nagazi PadampuEa.

66 | Page